


Reparatursatz zur Membranpumpe für 331, 321 & 301



Artikelnummer T206-321-100
beinhaltet pos. 1-14

Pos:	Anzahl	Zeichnungsnummer	Artikel
1	2	T07-100-009	Äussere Membrane, Viton
2	2	T07-100-010	Innere Membrane, Teflon
3	1	L70-604-2000	Saugschlauch, "Multi-Oil" 1/2" x 2.000 mm
4	2	L70-604-425	Saugschlauch, "Multi-Oil" 1/2" x 425 mm
5	1	L70-604-180	Saugschlauch, "Multi-Oil" 1/2" x 120 mm
6	1	L63-42-20-12	Kugellager, 6004 RS 42x20x12
7	2	L63-15-35-11	Kugellager, 6202 2RSH
8	1	L92-115-000	Äusserer Seegering 15 mm
9	8	L93-615-018	O-Dichtung 15,6 x 1,78 mm
10	10	L99-118-12-02	Dichtung, Viton Ø13x19x2 mm
11	4	L99-513-000	Stahlkugel Ø13, Edelstahl
12	4	T07-100-014	Ventilsitz für Pumpe 07
13	2	L82-508-016	Schraube, 8 x16 mm
14	1	L85-15-21-01	Dichtung, 15x21x1 mm

Presented by / Überreicht durch:

